AQM
BD LTD

INSPECTION REPORT

Final Inspection

Client Name:	PRODOUT LDA
Inspection No.:	0001
Report Date:	Feb 3, 2026

A. GENERAL INFORMATION

From: AQM BD LTD	To: nail.chakir@magazzino.pt
Contact:	Contact: Nail Chakir
Tel:	Tel:
Email: info@aqmbd.com	Email: nail.chakir@magazzino.pt
Inspector:	Copy To: NA

Date of Inspection:	Jan 3, 2026	**Product Description:**	Cooler Bag RECHEIO
Time Start:	11:00	**Item/Style/SKU:**	Cooler Bag RECHEIO
Time Finish:	16:00	**Purchase Order No.:**	A2632003
Inspection Location:	Anhui Province, China	**Letter of Credit:**	N/A
Vendor/Factory:	Factory China Anhui	**Country of Origin:**	China
		Destination:	Portugal
IFI Version:	N/A	**Protocol No:**	Inspection check.

B. INSPECTION RESULT (Refer to following pages for details)

	PASS				
PRODUCTS QUANTITY (Sec C)	X				
CONDITION OF PRODUCTS/PACKING (Sec D)	X				
CONDITION OF EXPORT CARTONS (Sec E)				X	
CONDITION OF CONTAINER(S) (Sec F)				X	
LOADING LOCATION & MONITOR (Sec G)				X	
SHIPPING MARKS (Sec H)				X	

OVERALL RESULT: **PASSED**

C. PRODUCTS QUANTITY

P.O. No.							
A2632003	Cooler Bag Rech	3600		3	3		
TOTAL							

D. CONDITION OF PRODUCTS/PACKING/ASSORTMENT

PASS * Correct product description / type / color / size and correct unit packaging / packing assortment.

FAIL * Missing or wrong product item, broken and lost basic function by observation, wrong item packaging or packing assortment, the product detached from the master carton and loaded into container directly.

E. CONDITION OF EXPORT CARTONS

PASS * Dry and in good working condition, free from serious damage, suitable for holding and protecting the said cargo, properly palletized.

FAIL * Crushed, with large holes, containing other serious damage, not suitable for holding and protecting the said cargo, improperly palletized.

AQM BD LTD counts and records the total number of export cartons loaded. By multiplication the inspector calculates the estimated total number of individual products. The inspector does not necessarily examine and/or count every individual product in the shipment. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.

F. CONDITION OF CONTAINER(S)

PASS * Dry and in good working condition, free from stains, bad odors, large dents and holes, suitable for loading the said cargo.

FAIL * Dirty, with stains, torn roof/side panels, broken hinges/handles or closure devices, etc.

G. CONDITION OF LOADING LOCATION & MONITOR OF LOADING PROCESS

Loading Location: [X] Factory [ ] Warehouse [ ] Other

Weather: [ ] Rainy [X] Sunny [ ] Snowy [ ] Other

Sheltered: [ ] Yes [X] No

PASS * All shipment cartons are loaded into container(s) completely. The cartons' loading process is safely and protected completely, free from contamination, dropping, brutality or overloading.

FAIL * Short loading, load product directly without master carton, brutality loading, carton dropped and soaked.

H. SHIPPING MARKS

Shipping Marks	Side Marks	Inner Box Marks

I. CONTAINER LOADING CHECK RESULT

Type							

J. REMARKS

1. Sample are in good condition , need to review , the color is ligher , no packaging made for the samples

Defect Photos:

Sample Photo outside - major

Sample photo Bottom - major

Sample photo inside - major

AQM BD LTD counts and records the total number of export cartons loaded. By multiplication the inspector calculates the estimated total number of individual products. The inspector does not necessarily examine and/or count every individual product in the shipment. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.



Sample photo inside - major

Sample Photo outside - major

Sample Photo outside - major

Sample photo inside - major

K. ATTACHMENTS

1. Digital Photos
2. Packing List

[X] FINAL REPORT

Report Reviewer:

Review Date: Feb 3, 2026

AQM BD LTD counts and records the total number of export cartons loaded. By multiplication the inspector calculates the estimated total number of individual products. The inspector does not necessarily examine and/or count every individual product in the shipment. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.